	er ID 59276 2010 2:16:14 PM										······································		Page 1
Item ID: Revision ID:	D3827-041				Accept					Setup		* *************************************	
		oard) art Qty: eq'd Qty				Cust Item II Customer:	D:				Stop		
Approvals:	Process Plan: _ QC:	/		Date: 10-5-2	Tooling: SPC (Y/N):	-	ite:		1	Run	Start Stop		
Sequence ID/ Work Center ID		eration cription	n		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr D3827	Revision Rev A	Nbr											
	Larg	ge Fab			0.00				6) /		/ / O· E	0648
Large Fab Large Fab			Iemo - cut D3827	-1 rib as per dwg D3827	0.00								
•		2	- drill holes	using DT9435 jig and op	en to finish size as per d	wg D3827							

SAD 10-08-15

3- c'sink as per dwg

7- grind weld flush8- deburr if necessary

5- deburr

4- remove identification markings

6- weld bushing in rib as per dwg D3827 A/R S.S. Rod Batch: 1110 79

Da	ırt	Aer	osi	pac	e Ltd	
----	-----	-----	-----	-----	-------	--

W/O:	0: WORK ORDER CHANGES								
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•	4					
									·
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date:	
		esolution:	·						
NCR:	NCR:		VORK ORE	DER NON-CONFORM	ANCE (NC	R)			, .
DATE	STEP	Description of NC Section A	Initial	Action Description	ion B Sign	& Sect	cation	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng	Date				
							:		
a a									
,									
NATE 6									-

W	ork	Order	· ID	59276
* * *	V 1 1 1 1 1 1 1 1 1	Oiuci		<i>- 2/4/0</i>

Friday, May 28, 2010 2:16:14 PM



Page 2

Item ID:

D3827-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Rib Assembly (Inboard)

Start Date:

Required Date: 6/4/2010

5/28/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

Tooling:

Date:

Date:

Run

Start

Stop

QC:____

Memo

Memo

Memo

Date:_____ **SPC (Y/N):**

Tool ID

Tool # Plan

Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Sequence ID/ **Work Center ID**

130

QC

Quality Control

Operation Description

QC10- Inspect visual per QSI004- ground welds

Set Up/ **Run Hours**

0.00

0.00

140

OC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

150

Packaging

Packaging

Identify as per dwg & Stock Location: (1)

0.00

0.00

10-06-17

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
									v					
Part No		PAR #:												
	Re	esolution:	Disposit	ion:	Q.	A: N/C CI	osed:		Date: _					
NCR:			WORK OR	DER NON-CON	FORMANC	E (NCF	₹)							
DATE	STEP	Description of NC Section A	Initial	Corrective Action Action Desc		Sign 8		cation	Approval Chief Eng	Approval QC Inspector				
		333,017	Chief Eng	Chief En		Date			Chief Eng	QC inspector				
				,										
								·						
·		•												

Work	Order	ID	59276
WULK	Oruer	1	374/0

Friday, May 28, 2010 2:16:14 PM



Page 3

Item ID:

D3827-041

Accept



Setup Start

Revision ID:

Rib Assembly (Inboard) **Item Name:**

Start Date: 5/28/2010 Required Date: 6/4/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Δ	nn	rova	ile•
7	PΡ	11 0 4 6	113.

Process Plan:

Date:

Tooling:

Date:

Run

Start

Stop



QC:

Date: SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID** Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**

Tool ID

Tool # Plan

Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

160

QC

Memo

0.00

0.00

10/06/17 d. MF 16-6-17

Quality Control

Dart Ae	rospace	Ltd							*
W/O:			WO	RK ORDER CHANGE	ES				
DATE	STEP	PRO	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		<u>``</u>							
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _	
	Re	solution:	Disposition	:	QA: N/C C	osed:	Date:		
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	₹)	1		
DATE		Description of NC		Corrective Action Section	Section B Verific			A	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	k Secti	on C	Approval Chief Eng	Approval QC Inspector
			**		9				
	4.								

Picklist Print

Friday, May 28, 2010 2:16:19 PM

Work Order ID: 59276

D3827-041

Parent Item Name: Rib Assembly (Inboard)

Parent Item:

IPP Rev: A 08-12-01 new issue DD verified by:EC



Start Date: 5/28/2010

Required Date: 6/4/2010


Page 1

Start Oty. 6.00

Component Item ID/ Item ID Replacement Mfg/ Item ID Replacement Mfg/ Item ID Replacement Replacement	Comments:	IPP Rev:A 08-12-	-01 new issue D	D veri	fied by:EC				S	Start Qty: 6.00		Requir	red Qty: 6.0	00
Bushing Location Loc Otv Loc Code B5 5 419					•					Qty per Kit				Status
S4072 9 58159 1 58256 26 58581 42 58672 36 36 58672 36 36 58672 36 36 36 36 36 36 36 3			Manufactured	No			100	Each	114.0000	_	18	(Gl	10.06.1
S4072 9 58159 1 58256 26 58581 42 58672 36 36 58672 36 36 58672 36 36 36 36 36 36 36 3					Location	1	Loc	<u>Otv</u>	Loc Code					
S8159 1					WA					D	<u> </u>	17-	>{	11)
S8256 26 58581 42 58672 36								9				-	(
M304TS0.750W.065 Purchased No 100 f 1,116.480 8 50.52632								1		_		-		
M304TS0.750W.065 Purchased No 100 f 1,116.480 8 50.52632										_		-		
M304TS0.750W.065 Purchased No 100 f 1,116.480 8 50.52632 304 SQ Tube .75x.75x.065W Location MAT 116.48021 112398 0 114482 116.48021 WA 1000 WA 1000										7		7		
304 SQ Tube .75x.75x.065W Location MAT 112398 114482 116.48021 WA 1000 WA 1000	M304TS0.750W.065		Purchased	No		20072	100		1 116 480	ş (50.52622	-/		
304 SQ Tube .75x.75x.065W Location Loc Oty Loc Code MAT 116.48021 112398 0 114482 116.48021 WA 1000							100	•	1,110.400				_	
MAT 116.48021	304 SQ Tube .75x.75x.065										SAU	/	10-0	6-15
112398 0 114482 116.48021 WA 1000					Location	<u>1</u>	Loc	<u>Oty</u>	Loc Code		+			
114482 116.48021 WA 1000					MAT		116.4	8021				_		
. WA 1000						112398		0				_		
WA 1000 114520 1000 50.5367						114482	116.4	8021				_		
114520 1000 50.52677					WA			1000					***	
						114520		1000		. <u> </u>	50.5	1637) .	


Dart A	erospace	Ltd
--------	----------	-----

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHAI	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector							
Part No	•	PAR #:	Fault Categ	Jory:	NCR: Yes	No DQA:	Date: _	1						
		esolution:												
NCR:			WORK ORDER NON-CONFORMANCE (NCR)											
DATE	STEP	Description of NC			ion B	Verification	Approval	Approval						
	J	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector						
					:									
· · · · · · · · · · · · · · · · · · ·														
							1							
														




Dart Aerospace Lte	d
--------------------	---

W/O:			WO	RK ORDER CHANG	ES	·	·		
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		,							
		·							
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQA:	Date: _		
		esolution:						Date:	
NCR:		V	VORK ORDE	R NON-CONFORMA	ANCE (NCF	₹)			
DATE	STEP	Description of NC Section A	Initial	Action Description	ion B		n Approval Chief Eng	Approval QC Inspector	
			Chief Eng	Chief Eng	Date	- Couron C	Onio. Ling	ac mapostor	
·									
\ \							-		
٠,				•				5	



Dart Aerospace L	Ltd
------------------	-----

W/O:			WC	ORK ORDER CHANG	ES			
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				<u>-</u>				
Part No:		PAR #:						
Resolution:		Disposition	1;	_ QA: N/C Cld	QA: N/C Closed: Date:			
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NCR)		
DATE	STEP	Description of NC		ion B	Verification	Approval	Approval	
DAIL	0121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
١	*,							
٠.,								
		I and the second	1 1			I	1	1



Dart	Aer	osp	ace	Ltd
------	-----	-----	-----	-----

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							•			•	
Part No:	:	PAR #:	Fault Cate	gory:	NCI	R: Yes	No DQ	A:	Date:		
			n: Disposition:								
NCR:				ER NON-CONFORM							
DATE STEP					ction B		Verific	Verification	Approval	Approval	
Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector			
					3			•			
										٠.	
			,								
• 4										-	
		-							·		
. '									•		
•		,									